Annexure D

BUILDING SAFETY CERTIFICATE

No. 11/Supdt/Structural Soundness/2025,

Dated: 29-03-2025

It is certified that the existing building <u>GVK Chinmaya Vidyalaya</u> (name of the building or premises) at <u>Kothur (V), Indukurpet (M), SPSR Nellore District</u> (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in	Block	Block	Block	Block	Block	Block
school	(1)	(2)	(3)	(4)	(5)	(6)
No. of Floor(s) in the	G+3					
Block						

The building is owned/occupied by <u>GVK Chinmaya Vidyalaya</u> (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of <u>Executive Engineer</u>, <u>R&B Division</u>, <u>Nellore</u>, <u>Govt of Andhra Pradesh</u> (Name of Department/ Govt.) on 29.03.2025 (date of inspection) in the presence of <u>B. Haritha Principal</u> (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from <u>29.03.2025</u> for a period of One (1) years in accordance with rule and subject to compliance of the specific conditions as appended.

1. 2. -NIL-3.

Issued on 29-03-2025 at 3.00 PM

4.

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.



Signature with Seal Division: NELLORE
Name: Y. Murali Krishna

Designation : Executive Engineer

Name & Address of Department/ Office: (R&B) Division, Near RDOs Office Compound, Nellore -524001